



















READ AND SAVE THIS INSTRUCTIONS FOR FUTURE USE

Tools Recommended

ASSEMBLY INSTRUCTION



<p>A</p>  <p>x 4</p> <p>Φ6X35mm</p>	<p>B</p>  <p>x 4</p> <p>Φ15X9mm</p>	<p>C</p>  <p>x 12</p> <p>M5x40mm</p>	<p>D</p>  <p>x 16</p> <p>M3.5x14mm</p>	<p>E</p>  <p>x 6</p> <p>M3x14mm</p>
<p>F</p>  <p>x 16</p> <p>Φ8x30mm</p>	<p>G</p>  <p>x 2</p> <p>M4x12mm</p>	<p>H</p>  <p>x 8</p>	<p>I</p>  <p>x 2</p>	<p>J</p>  <p>x 6</p>
<p>K</p>  <p>x 3</p>	<p>L</p>  <p>x 2</p>	<p>M</p>  <p>x 2</p>	<p>N</p>  <p>x 2</p>	<p>O</p>  <p>x 2</p> <p>M4x35mm</p>
<p>P</p>  <p>x 2</p>	<p>Q</p>  <p>x 1</p> <p>Ø4mm</p>			

