


# PawHut

INdcb086\_GL


**D51-069**




IMPORTANT, RETAIN FOR FUTURE REFERENCE: READ CAREFULLY

## ASSEMBLY & INSTRUCTION MANUAL


**PARTS**




**A**




**B**




**C\*4**




**D\*2**




**E\*2**




**F\*2**



**G\*2**



**H\*2**



**I**



**J**



**K\*2**

**HARDWARE**



3.5\*25mm 8+1pcs

**S1**



3.5\*20 mm 20+2pcs

**S2**



3.0\*18 mm 11+1pcs

**S3**



3.0\*12 mm 4pcs

**S4**



2.5\*10 mm 40+2pcs

**S5**



4pcs

**S6**



2pcs


**S7**



4pcs

**S8**

**A** x01




**C** x02




**S2**x04



3.5\*20mm



**B** x01




**C** x02




**S2**x04




3.5\*20mm




**E** x02



**F** x02



**G** x02



**S6** x04



**S7** x02



**S2** x04





3.5\*20mm


**S5** x40




2.5\*10mm



**01**



**02**




**D** x02



**S2** x08



3.5\*20mm



03



04




S1x08



3.5\*25mm


S5\*8



Hx02




S8x04




S8\*2

x2







05



06




I x01



S4 x04


3.0\*12mm




x2

S4\*2


I




06



J x01




K x02



S3 x11

3.0\*18mm



K\*2

J

S3\*11